

**Flood Control Project Maintenance
Levee Inspections
2008 Channel Summary Report
Overall Unit and Item Ratings**

Adin Community Service District

Ash Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	M

Dry Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	A

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

Adin Community Service District

Channel
Ash Creek

Date of Inspection	9/16/2008
DWR Inspector	Bob Duffey
Channel Rating	A

Flood Control Project Maintenance
Inspection Report - Channel 2008

Adin Community Service District

Channel				Inspection Date	Inspector	
Ash Creek				09/16/2008	Bob Duffey	

Rpt Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Structures & Concrete Lined Channels	Concrete Foundations		A		41.192990 ° 120.954530 °	Y	6
2	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		41.197770 ° 120.944100 °	Y	1
3	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		41.197660 ° 120.944220 °		2
4	Rivers, Channels & Designated Floodways	Erosion		M		41.197660 ° 120.944220 °	Y	3
5	Rivers, Channels & Designated Floodways	Erosion		M		41.197140 ° 120.945280 °	Y	5
6	Rivers, Channels & Designated Floodways	Concrete Foundations		A		41.192990 ° 120.954530 °	Y	4

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Channel 2008

Adin Community Service District

Channel	Inspection Date	Inspector
Ash Creek	09/16/2008	Bob Duffey

Report Line	1
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations
Dam with fish ladder and metal walkway, constructed Oct. 1999 by the Dept. of Fish & Game	



Report Line	2
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
From Main Street (Highway 299) towards the gauging station	



Report Line	2
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
From Main Street (Hwy. 299) at the Ash St. low water crossing	

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable

PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected

C : Corrected

Flood Control Project Maintenance
Inspection Report - Channel 2008

Adin Community Service District

Channel	Inspection Date	Inspector
Ash Creek	09/16/2008	Bob Duffey

Report Line	4
Location	
Category	Rivers, Channels & Designated Floodways
Item	Erosion
From Ash Street moderate tree growth and bank erosion	



Report Line	5
Location	
Category	Rivers, Channels & Designated Floodways
Item	Erosion
Downstream at a sharp left bend moderate erosion on both banks	



Report Line	6
Location	
Category	Rivers, Channels & Designated Floodways
Item	Concrete Foundations
Upstream from the downstream limit	

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable

PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected

C : Corrected

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

Adin Community Service District

Channel
Dry Creek

Date of Inspection	9/16/2008
DWR Inspector	Bob Duffey
Channel Rating	A

Flood Control Project Maintenance
Inspection Report - Channel 2008

Adin Community Service District

Channel	Inspection Date	Inspector
Dry Creek	09/16/2008	Bob Duffey

Rpt Line	Category	Item	* Location	** Rating	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		41.195370 ° 120.943190 °	Y	1
2	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		41.195370 ° 120.943190 °	Y	2
3	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		41.196350 ° 120.944250 °	Y	3
4	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		41.196350 ° 120.944250 °	Y	4

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Channel 2008

Adin Community Service District

Channel	Inspection Date	Inspector
Dry Creek	09/16/2008	Bob Duffey

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream at Cedar Street moderate growth in channel	



Report Line	2
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Upstream at Cedar Street minimal growth in channel	



Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream from Main Street (Hwy 299) moderate growth in channel	

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable

PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected

C : Corrected

Flood Control Project Maintenance
Inspection Report - Channel 2008

Adin Community Service District

Channel	Inspection Date	Inspector
Dry Creek	09/16/2008	Bob Duffey

Report Line	4
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from Main street (Hwy 299) minimal growth in channel

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected